

## Historic Flooding Documentation

To gather flood information not captured in formal reports, studies, or models, a stormwater and flood resilience questionnaire was developed and mailed to approximately 1,400 properties within the City's FEMA SFHA and RPA as part of its Resilience Plan efforts. The questionnaire asked residents if flooding occurs in their area, how often it occurs, if the resident feels that the City's infrastructure has the capacity to handle flooding, if they feel informed about flooding and flood risk, and included an additional section for residents to provide comments or any flooding related pictures. The following images have been sourced from the City's flood resilience questionnaire. These images and the additional data included as part of the City's Resilience Plan serve as documentation of flooding in proximity to the Stafford Drive culvert. Personally Identifiable Information, such as names and addresses of residents who have submitted questionnaire data, has not been included as part of this grant application.

Additional information on flooding in the Mosby Woods and Stafford Drive area can also be found in the Mosby Woods Floodplain Improvements Study, which has been included as part of this grant application for reference.



Ranger Road Park Flooding, Downstream of Stafford Drive



Cambridge Station Flooding, Downstream of Stafford Drive